

FOIL C2043W,1:

Is a badly scratched foil

Observed 5 craters $> 0.2 \mu\text{m}$ and $< 5 \mu\text{m}$ in diameter at some 500 x of approx.50% of foil surface.

4 craters contain Mg, Si, S and Fe in variable proportions

1 contains Fe + Cr (stainless steel ??)

Foil does not display enough craters to do a meaningful statistical survey; no craters $> 5 \mu\text{m}$